

Welding Processes



- **EN358 – Ship Structures**




A Brief History of Welding

- Late 19th Century
 - Scientists/engineers apply advances in electricity to heat and/or join metals (Le Chatelier, Joule, etc.)
- Early 20th Century
 - Prior to WWI welding was not trusted as a method to join two metals due to crack issues
- 1930's and 40's
 - Industrial welding gains acceptance and is used extensively in the war effort to build tanks, aircraft, ships, etc.
- Modern Welding
 - the nuclear/space age helps bring welding from an art to a science



Types of Welding



Weldability of a Metal

- Metallurgical Capacity
 - Parent metal will join with the weld metal without formation of deleterious constituents or alloys
- Mechanical Soundness
 - Joint will be free from discontinuities, gas porosity, shrinkage, slag, or cracks
- Serviceability
 - Weld is able to perform under varying conditions or service (e.g., extreme temperatures, corrosive environments, fatigue, high pressures, etc.)




Fusion Welding Principles

- Base metal is melted
- Filler metal may be added
- Heat is supplied by various means
 - Oxyacetylene gas
 - Electric Arc
 - Plasma Arc
 - Laser



Fusion Welding



Weld Metal Protection

- During fusion welding, the molten metal in the weld “puddle” is susceptible to oxidation
- Must protect weld puddle (arc pool) from the atmosphere
- Methods
 - Weld Fluxes
 - Inert Gases
 - Vacuum



Weld Fluxes

- Typical fluxes
 - SiO_2 , TiO_2 , FeO , MgO , Al_2O_3
 - Produces a gaseous shield to prevent contamination
 - Act as scavengers to reduce oxides
 - Add alloying elements to the weld
 - Influence shape of weld bead during solidification



Inert Gases

- Argon, helium, nitrogen, and carbon dioxide
- Form a protective envelope around the weld area
- Used in
 - MIG
 - TIG
 - Shield Metal Arc



Vacuum

- Produce high-quality welds
- Used in electron beam welding
- Nuclear/special metal applications
 - Zr, Hf, Ti
- Reduces impurities by a factor of 20 versus other methods
- Expensive and time-consuming




Types of Fusion Welding

- Oxyacetylene Cutting/Welding
- Shielded Metal Arc (“Stick”)
- Metal Inert Gas (MIG)
- Tungsten Inert Gas (TIG)



Oxyacetylene Welding

- Flame formed by burning a mix of acetylene (C_2H_2) and oxygen



- Fusion of metal is achieved by passing the inner cone of the flame over the metal
- Oxyacetylene can also be used for cutting metals



Shielded Metal Arc (Stick)

- An electric arc is generated between a coated electrode and the parent metal
- The coated electrode carries the electric current to form the arc, produces a gas to control the atmosphere and provides filler metal for the weld bead
- Electric current may be AC or DC. If the current is DC, the polarity will affect the weld size and application



Shielded Metal Arc (con't)

- Process:
 - Intense heat at the arc melts the tip of the electrode
 - Tiny drops of metal enter the arc stream and are deposited on the parent metal
 - As molten metal is deposited, a slag forms over the bead which serves as an insulation against air contaminants during cooling
 - After a weld 'pass' is allowed to cool, the oxide layer is removed by a chipping hammer and then cleaned with a wirebrush before the next pass.




Inert Gas Welding

- For materials such as Al or Ti which quickly form oxide layers, a method to place an inert atmosphere around the weld puddle had to be developed




Metal Inert Gas (MIG)

- Uses a consumable electrode (filler wire made of the base metal)
- Inert gas is typically Argon




Tungsten Inert Gas (MIG)

- Tungsten electrode acts as a cathode
- A plasma is produced between the tungsten cathode and the base metal which heats the base metal to its melting point
- Filler metal can be added to the weld pool



Welding Positions



Weld Defects

- Undercuts/Overlaps



- Grain Growth

- A wide ΔT will exist between base metal and HAZ. Preheating and cooling methods will affect the brittleness of the metal in this region

- Blowholes

- Are cavities caused by gas entrapment during the solidification of the weld puddle. Prevented by proper weld technique (even temperature and speed)



Weld Defects

- Inclusions
 - Impurities or foreign substances which are forced into the weld puddle during the welding process. Has the same effect as a crack. Prevented by proper technique/cleanliness.
- Segregation
 - Condition where some regions of the metal are enriched with an alloy ingredient and others aren't. Can be prevented by proper heat treatment and cooling.
- Porosity
 - The formation of tiny pinholes generated by atmospheric contamination. Prevented by keeping a protective shield over the molten weld puddle.




Residual Stresses


- Rapid heating and cooling results in thermal stresses detrimental to joint strength.
- Prevention
 - Edge Preparation/Alignment – beveled edges and space between components to allow movement
 - Control of heat input – skip or intermittent weld technique
 - Preheating – reduces expansion/contraction forces (alloys) and removes moisture from the surface
 - Peening – help metal stretch as it cools by hitting with a hammer. Use with care since it may work harden the metal
 - Heat Treatment – “soak” the metal at a high temperature to relieve stresses
 - Jigs and Fixtures – prevent distortion by holding metal fixed
 - Number of Passes – the fewer the better.




Joint Design




BUTT JOINT




FILLET JOINT



STRAP JOINT




LAP JOINT



CORNER



Generalized Welding Symbol



ARROW SIDE DETAILS

D = Weld Depth (usually equal to plate thickness)



L1 = Weld Length

L2 = Distance between centers for stitched welds

The Field Weld Symbol is a guide for installation. Shipyards normally do not use it, except in modular construction.






Example Welding Symbol







Geometry symbol for V-groove


One-sided welds are max 80% efficient
Two sided are 100% efficient



Weld Symbols (Butt Joints)



Weld Symbol (Fillet Joints)



Weld Symbol (Corner Joints)

